

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) 801-538-5319 (TDD)

May 2, 1994

Mr. Thomas E. Ehmett, Acting Director Office of Surface Mining Reclamation and Enforcement 505 Marquette N.W., Suite 1200 Albuquerque, New Mexico 87102

Re: <u>Updated Plate 5-3, Surface Facility Map, Genwal Coal</u>
<u>Company, Crandall Canyon Mine, ACT/015/032-94C, Folder #2,</u>
<u>Emery County, Utah</u>

Dear Mr. Ehmett:

Enclosed please find the approved Plate 5-3 for the Crandall Canyon Mine that includes culvert C-5 and the four-inch pipeline west of C-5 within the disturbed area boundary.

Sincerely,

Pamela Grubangh-Litti

Permit Supervisor

cc: Richard Dawes, OSM, Denver
Mark Bailey, BLM, Price
George Morris, Manti-LaSal FS
Brent Bradford, DEQ
Robert Valentine, DWR
Scott Hirschi, State Lands